




Chenoweth Roofing was at the Coldwater Branch on November 19th and 20th to address our warranty claim. Here's a comparison of the same areas before and after the warranty work. I have forwarded all these pictures to Ken Fickle at the Coldwater city inspector's office. I'm awaiting word on their opinion of the repair job.

Submitted by,
John Rucker










Poorly flashed
northeast side



Shingles appear to be improperly installed
southeast side





This spot cannot be seen from the ground, so no new picture available.



It's clear that some work was done from the ground, but this is the best view we have. Chenoweth worker said flashing had been



3rd floor leak, west side of 1979 portion of building



improperly installed here.



**New active leak (red)
above old main
entrance in local
history room**

Cause of this leak was determined by
Chenoweth workers to be a piece of detached
flashing.

